



120 East Davis Street
Fayette, MO 65248-1405
(660) 248-1911
www.inovatia.com

Date: 9/13/2023

RE: Drinking Water Lead Analysis
Facility: Putnam County R-1

Date Received: 08/14/23
Time Received: 08:15
Relinquished by: Bob Franklin
Sampler: Bob Franklin

Chain of Custody Number: Pb-0054

Enclosed please find results for the sample(s) received as described above. The values reported are in conformance with internal and method quality control guidelines.

If you have questions or need more information, please contact us.

Thank you for your interest in working with Inovatia Laboratories.

Sincerely,

A handwritten signature in black ink that reads "Jennifer Vandelight". The signature is written in a cursive, flowing style.

Jennifer Vandelight
Quality Assurance

Note: Testing Performed by NELAC Facility E87688

Enclosures:
Chain of Custody Record(s)



Analysis Report

Total Lead by ICP-MS

Chain of Custody: Pb-0054
Facility: Putnam County R-1

Sample Matrix: Water
Method of Analysis: EPA 200.8

| Laboratory Number | Customer Sample Number | Date Collected | Sample Type | Result ug/L (ppb) | Reporting Limit |
|-------------------|-------------------------------|----------------|-------------|----------------------|--------------------|
| Pb-0054-001 | PTM01-HS29-FBCH-SH FF-001 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-002 | PTM01-HS29-FBCH-HS FF-002 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-003 | PTM01-HS30-BBCH-HS FF-003 | 8/8/2023 | Flush | 2.27 | 1.0 |
| Pb-0054-004 | PTM01-GLKR-HS32-SH1 FF-004 | 8/8/2023 | Flush | 11 | 1.0 |
| Pb-0054-005 | PTM01-GLKR-HS32-SH2 FF-005 | 8/8/2023 | Flush | 178 | 1.0 |
| Pb-0054-006 | PTM01-GLKR-HS32-SH3 FF-006 | 8/8/2023 | Flush | 265 | 1.0 |
| Pb-0054-007 | PTM01-GLKR-HS32-SH4 FF-007 | 8/8/2023 | Flush | 10.6 | 1.0 |
| Pb-0054-008 | PTM01-GLKR-HS32-SH5 FF-008 | 8/8/2023 | Flush | 14.8 | 1.0 |
| Pb-0054-009 | PTM01-HS28-FACS-FP4-SC FF-009 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-010 | PTM01-HS28-FACS-FP4-SC FF-010 | 8/8/2023 | Flush | 1.3 | 1.0 |
| Pb-0054-011 | PTM01-KITCH-SC1 FF-011 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-012 | PTM01-KITCH-SC2 FF-012 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-013 | PTM01-KITCH-SC3 FF-013 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-014 | PTM01-KITCH-IM FF-014 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-015 | PTM01-MS9-DFL FF-015 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-016 | PTM01-MS9-DWL FF-016 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-017 | PTM01-HS22-DF FF-017 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-018 | PTM01-HS2-DW FF-018 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-019 | PTM01-EL20-DW FF-019 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-020 | PTM01-EL23-HS FF-020 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-021 | PTM01-BSBL-CONC-RRFB FF-021 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-022 | PTM01-SB-CONC-HS1 FF-022 | 8/8/2023 | Flush | 2.67 | 1.0 |
| Pb-0054-023 | PTM01-HS34-GLKR-HS FF-023 | 8/8/2023 | Flush | 2.64 | 1.0 |
| Pb-0054-024 | PTM01-SOAR-HS2 FF-024 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-025 | PTM01-FB-NTH-LKR-SHL FF-025 | 8/8/2023 | Flush | ND | 1.0 |
| Pb-0054-026 | PTM01-EL22-HS-SC FF-026 | 8/8/2023 | No Sample | | |
| Pb-0054-027 | PTM01-EL22-HS-SC PS-001 | 8/8/2023 | No Sample | | |



120 East Davis Street
 Fayette, MO 65248-1405
 (660) 248-1911
 www.inovatia.com

Contact Name: Bob Franklin
 Company Name: Get the Lead Out LLC
 Address: PO Box 118
 City, State, zip: Sturgeon, MO 65284
 Phone Number: 417-294-6112
 E-Mail: bobfranklin@gettheleadoutmo.us

Matrix: Water
 Grab/Composite: Grab
 Number of Containers: 27
 Preservation: HNO3
 Chain of Custody: Pb-0054-001

Facility: Putnam Co. R-I
 Facility Address: 803 S 20th Unionville, MO 63565-1482
 Facility Contact: Heath Halley

| Lab Number | Customer Sample Number | Date Collected | |
|------------|------------------------|-------------------------------|----------|
| 1 | Pb-0054-001 | PTM01-HS29-FBCH-SH FF-001 | 8/8/2023 |
| 2 | Pb-0054-002 | PTM01-HS29-FBCH-HS FF-002 | 8/8/2023 |
| 3 | Pb-0054-003 | PTM01-HS30-BBCH-HS FF-003 | 8/8/2023 |
| 4 | Pb-0054-004 | PTM01-GLKR-HS32-SH1 FF-004 | 8/8/2023 |
| 5 | Pb-0054-005 | PTM01-GLKR-HS32-SH2 FF-005 | 8/8/2023 |
| 6 | Pb-0054-006 | PTM01-GLKR-HS32-SH3 FF-006 | 8/8/2023 |
| 7 | Pb-0054-007 | PTM01-GLKR-HS32-SH4 FF-007 | 8/8/2023 |
| 8 | Pb-0054-008 | PTM01-GLKR-HS32-SH5 FF-008 | 8/8/2023 |
| 9 | Pb-0054-009 | PTM01-HS28-FACS-FP4-SC FF-009 | 8/8/2023 |
| 10 | Pb-0054-010 | PTM01-HS28-FACS-FP4-SC FF-010 | 8/8/2023 |
| 11 | Pb-0054-011 | PTM01-KITCH-SC1 FF-011 | 8/8/2023 |
| 12 | Pb-0054-012 | PTM01-KITCH-SC2 FF-012 | 8/8/2023 |
| 13 | Pb-0054-013 | PTM01-KITCH-SC3 FF-013 | 8/8/2023 |
| 14 | Pb-0054-014 | PTM01-KITCH-IM FF-014 | 8/8/2023 |
| 15 | Pb-0054-015 | PTM01-MS9-DFL FF-015 | 8/8/2023 |
| 16 | Pb-0054-016 | PTM01-MS9-DWL FF-016 | 8/8/2023 |
| 17 | Pb-0054-017 | PTM01-HS22-DF FF-017 | 8/8/2023 |
| 18 | Pb-0054-018 | PTM01-HS2-DW FF-018 | 8/8/2023 |
| 19 | Pb-0054-019 | PTM01-EL20-DW FF-019 | 8/8/2023 |
| 20 | Pb-0054-020 | PTM01-EL23-HS FF-020 | 8/8/2023 |
| 21 | Pb-0054-021 | PTM01-BSBL-CONC-RRFB FF-021 | 8/8/2023 |
| 22 | Pb-0054-022 | PTM01-SB-CONC-HS1 FF-022 | 8/8/2023 |
| 23 | Pb-0054-023 | PTM01-HS34-GLKR-HS FF-023 | 8/8/2023 |
| 24 | Pb-0054-024 | PTM01-SOAR-HS2 FF-024 | 8/8/2023 |
| 25 | Pb-0054-025 | PTM01-FB-NTH-LKR-SHL FF-025 | 8/8/2023 |
| 26 | Pb-0054-026 | PTM01-EL22-HS-SC FF-026 | 8/8/2023 |
| 27 | Pb-0054-027 | PTM01-EL22-HS-SC PS-001 | 8/8/2023 |

3? no samples 26/27

Delivery Method: Hand
 Coolant: —
 Arrival Temperature: —

Sampler Signature: *[Signature]*

Date/Time: 8/8/2023-0615

Relinquished By: BOB FRANKLIN

Date/Time: 8/14/2023 - 0815

Received By: *[Signature]*

Date/Time: 8/14/2023 0815